BYU | CIVIL & ENVIRONMENTAL ENGINEERING

IRA A. FULTON COLLEGE




CEEn-2016CPST-003

LID APPROACH EFFECTIVENESS & FUNCTIONALITY STUDY

Team LID

Mentor: John De Leon Treyton Moore Jingwen He Kevin Liang



IRA A. FULTON COLLEGE



Design, Analysis & Results

- 90th percentile storm = 0.54in
- LID systems exceeded EPA standards in Spanish Fork
 - Total runoff volume = 2301 ft³
 - Total system volume = 4635 ft³
 - LID performance varied for the 5, 10, 25, 50, and 100 year storms depending on soil quality.
 - Poor soil drainage caused R-tanks to overtop in these cases analyzed
 - Leaf build up in entrance R-tank
 - Poor initial layout of R-tanks by contractors resulting in complications

IRA A. FULTON COLLEGE

Storm Intensities	Runoff Volume (pcf)	Drainage Time (hrs)
100 years storm	28002	0.306
50 years storm	23727	0.259
25 years storm	19608	0.214
10 years storm	14730	0.161
5 years storm	11274	0.123
90th percentile storm	2301	0.025


BYU | CIVIL & ENVIRONMENTAL ENGINEERING IRA A. FULTON COLLEGE





BYU | CIVIL & ENVIRON IRA A. FULTO

- Use water meter out silt build up
- For future syster entrance and "fill
- **Improve inspect**
- For sites with po stacked deeper t



- "SNOUT" OIL-WATER-DEBRIS SEPARATOR SHALL BE INSTALLED TO MANUFACTURER'S SPECIFICATIONS.
- ALL PLANTER AREAS BETWEEN THE CURB AND SIDEWALK SHALL BE LANDSCAPED WITH PERVIOUS MATERIALS UNLESS OTHERWISE APPROVED BY THE CITY ENGINEER OR DESIGNEE.