BYU | CIVIL & ENVIRONMENTAL ENGINEERING





Project Status Report: CEEn-2017CPST-001: Arrowhead Center (Structural and Geotechnical)

Team Members: Austin Burton, Kendl Hansen, David Davies

Date: January 29, 2018

1)	Summar	y of technical/non-technical challenges encountered
	Summai.	of teeninear non-teeninear chancinges encountered

- Setting up a site visit.
- Obtaining building plans.
- Communication issues regarding expectations.

2) Team approaches/resolutions to overcome challenges

- Worked with John Ashworth to schedule a site visit.
- Reached out to Mitch, Bob, LEI for more information. We eventually came to the conclusion that we could obtain the necessary information from the site visit.
- Contacted the city of Spanish Fork to obtain structural plans.

3) Status of challenge resolutions & potential project impacts

- Site visit is scheduled for February 3rd. We will have access to the building and be able to take measurements of the structural members to determine adequacy.
- We are still currently waiting on a response from the city of Spanish Fork about the plans.

4) Project Status & Summary

- We are currently determining what reports and studies are necessary for proposals 004 and 005.
- Preparing for the site visit.